

MONUMENT RECORD

Corner I.D. #


W-5

STATE OF INDIANA - COUNTY OF MONROE

Section Twelve (12), Township 9 North, Range 1 West

Monument Description & Remarks: Found Sandstone Stone w/"X" at North 1/4
corner, 0.3' x 0.8' x 0.2' out of ground. Stone was solid in ground &
marked w/purple fence post. Survey marker sign & post set.

Recovery Tie Drawing



● At Corner



Not To Scale

State of Indiana
County of Monroe

I, Michael W. Friley, County Surveyor, hereby certify
that this document was prepared under my direction in
accordance with the provisions of Section 17-3-64-4
through 17-3-64-8 of the Indiana Code, being Acts of 1965,
Chapter 319; and the above data is given under my hand and
seal this 24th day of April, 19 95 A.D.

Space
Reserved For
Recording
Officer

Indiana Registered Land Surveyor No. _____ or

Office of Monroe County Surveyor
United States Government Agency

Monroe County Surveyor
Title

Field Book:

95-01

Page:

31